



Western Michigan University
ScholarWorks at WMU

Legacy Scout Tickets from Pure Oil Company

8-20-2021

MGRRE_PureOilScoutTickets_Ruess, J._1_21159062030000

MGRRE

Western Michigan University

Follow this and additional works at: <https://scholarworks.wmich.edu/pure>



Part of the Geology Commons

WMU ScholarWorks Citation

MGRRE, "MGRRE_PureOilScoutTickets_Ruess, J._1_21159062030000" (2021). *Legacy Scout Tickets from Pure Oil Company*. 10045.

<https://scholarworks.wmich.edu/pure/10045>

This Document is brought to you for free and open access via ScholarWorks at WMU. It has been accepted for inclusion in Legacy Scout Tickets from Pure Oil Company by an authorized administrator of ScholarWorks at WMU. See the National Digital Catalogue - Science Base Catalogue for more collections submitted by MGRRE.



MGRRE_PureOilScoutTickets_Ruess, J._1_21159062030000

API 21159062030000

Permit Number 6203

Lease Name Ruess, J.

Well Number 1

County Van Buren

Township 01S

Range 15W

Section 3

2021 DEQ or Pure co_name Rose, Louis

Pure Number 429

Latitude 42.40654

Longitude -86.036

The Pure Oil Company
COMPLETION RECORD OF WELLS DRILLED BY OTHER OPERATORS
THE PURE OIL COMPANY

DATE May 25, 1939

LOCATION REPORT

No. 429

STATE Michigan COUNTY Van Buren DIST. Columbia SEC. 3 TOWN 11 S RANGE 15 W
WELL No. 11 (SERIAL No. 429) FARM J. Ruess ACRES

NAME OF STREAM OR WATERS _____ QUADRANGLE C. 51-N1-SE-SE
C. 51-N1-SE-SE

OPERATOR Louis Rose Map Columbia Township, Van Buren County
Louis Rose Columbia - Van Buren

Feet from North Line of Farm

<u>660</u>	<u>660</u>	"	"	East	"	"	"
<u>272</u>	<u>272</u>	"	"	South	"	"	"
<u>660</u>	<u>660</u>	"	"	West	"	"	"

Feet from North Line of Section

<u>660</u>	<u>660</u>	"	"	East	"	"	"
<u>826</u>	<u>826</u>	"	"	South	"	"	"
		"	"	West	"	"	"

LEGEND

○ LOCATION

① RIG

⊕ DRILLING

☀ GAS WELL

● OIL WELL

⦿ SMALL OIL WELL

⊖ DRY HOLE

⦿ DRY SHOWING OIL


⊖ DRY SHOWING GAS

⊖ ABANDONED LOCATION

☀ ABANDONED GAS WELL

⦿ ABANDONED OIL WELL

NOTE: Below make tracing from map, (when no map is obtainable make sketch) showing farm, center of section, this location with measurements and also wells, dry holes, or other locations in the vicinity of this location.



REMARKS:

SIGNED

Superintendent or Foreman.

D. C. Shackelford